


VOLKSWAGEN PASSAT VARIANT: 1WDP947

Vinnumber:	WVWZZZ3CZKE096896	Versionname:	1.6 TDI Highline Business DSG-7
First Registrationdate:	6/05/2019	Fiscalpower:	
Expertise Mileage:	100018	Power Kw:	88
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1330
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting:	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining semi-Alcantara		
Type of climate control:	Autom climate control		
Adaptive cruise control			
Type of GPS storage:	HD		

Limited Technical Inspection
Degree of wear

215/55/17/88 V				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				215/55 R 17 88 V
Tyre type FL				All season
Tyre make FL				264
Tyre make RL				264

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1075,99
-------------------	---------

Wing RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Tailgate / Boot, Not original part, Sticker removal small	0,00
---	------



Alloy rim RR, Scratch(es), Repair and paint (complete)

125,40



Bonnet, Stone chip(s), Acceptable

0,00



Alloy rim FL, Scratch(es), Repair and paint (complete)

125,40



Door FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Door RR, Dent(s) and scratch(es), Repair and paint (complete)

420,22



Roof, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Door FR, Scratch(es), Acceptable

0,00



Wing FR, Scratch(es), Acceptable

0,00



Wing FL, Scratch(es), Acceptable

0,00



Wing RR, Scratch(es), Acceptable

0,00



Bumper F, Stone chip(s), Acceptable

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

125,40



Bumper R, Scratch(es), Repair and paint (complete)

279,57

