


Volvo V 60: 1WVK088

Vinnumber:	YV1ZW72VDL1352437	Versionname:	
First Registrationdate:	19/07/2019	Fiscalpower:	
Expertise Mileage:	191482	Power Kw:	110
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Steel
Transmission:		Parking lot:	4705
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection
Degree of wear

225/50/17/98 H				
Winter tyres:	Fr.L.	BF Goodrich: 4 mm	Fr.R.	BF Goodrich: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/50 R 17 98 H
Tyre type FL				Winter
Tyre make FL				2485
Tyre make RL				2480


Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	991,41
Bumper R, Scratch(es), Spot repair	197,83



Roof, Chemical polution, Repair and paint (complete)	693,58
--	---------------



Door FR, Scratch(es), Paint (partial)	100,00
---------------------------------------	--------



Door trim FL, Scratch(es), Polish	0,00
-----------------------------------	------



Rear window, Scratch(es), Replace	0,00
-----------------------------------	------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

